#### **DEPARTMENT OF TRANSPORTATION**

**DIVISION OF ENGINEERING SERVICES** Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.15

## SOURCE INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** SIR-000355 Address: 333 Burma Road **Date Inspected:** 19-Dec-2008

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Location: Changxing Dao, Shangha

**Quality Control Contact:** William (Bill) Oak **Quality Control Present:** Yes No

N/A **Material transfer:** Yes No **Sampled Items:** Yes No N/A **Stock Transfer:** Yes N/A OK to Cut: N/A No Yes No **Rebar Test Witness:** Yes N/A **Delayed/Cancelled:** N/A No Yes No

Other: Coatings Inspection

**Bridge No:** 34-0006 **Component: Bid Item:** 77.78.79 Lot No:

#### **Summary of Items Observed:**

METS acquired paint samples from the paint storage area that arrived late yesterday afternoon. Batch Numbers were Interzinc 22 Part A: JM4584PV and Part B: JF0963PV.

Interzinc 52 Part A: JL3998PV and Part B: JL4127PV

1 container of each will sent to Shanghai, China Lab, Supervising Center of Shanghai Research Institute of Paint and Coatings (SCSPC) for testing with TL-101 Card Number C726901 attached.





#### **Summary of Conversations:**

# SOURCE INSPECTION REPORT

(Continued Page 2 of 2)

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wabeh (China) +8613472477571, who represents the Office of Structural Materials for your project.

Inspected By:	Jordan,Don	Quality Assurance Inspector
Reviewed By:	Mertz,Robert	QA Reviewer